

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2026

Submitted Date:

01/26/2026

Document Number:

719001219

FIELD INSPECTION FORM

Loc ID 333412 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215068	WELL	PR	11/30/2004	CBM	067-06673	SCHALLES -A- 1	PR
292003	WELL	PR	07/01/2011	CBM	067-09387	FLAGG 6-3	PR

General Comment:

Inspection Report Summary
On 1/26/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: FLAGG 6-3, SCHALLES A #1
API# 067-09387
API# 067-09387
Operator: HILLCORP ENERGY COMPANY
County: LaPlata
GATE CAMB0 7708

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	SOUND WALLS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked			# 4
Comment:			ALL DEADMEN UNMARKED
Corrective Action:			Date:
Type: Bird Protectors			# 2
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator			# 2
Comment:			
Corrective Action:			Date:
Type: Pump Jack			# 2
Comment:			
Corrective Action:			Date:
Type: Other			# 2
Comment:			METER HOUSES CALIBRATION IN COMPLIANCE
Corrective Action:			Date:
Type: Gas Meter Run			# 2

Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	2 TELEMETRY EQUIPMENT 2 LUBE OIL CONTAINERS FOR PTIME MOVERS 1 WITH SPILL PREVENTION 1 WITHOUT SEE LOCATION PICTURES		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Comply with rule 1002.f		Date: 01/29/2026

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404519585	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7427385
719001220	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7427382