

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2026

Submitted Date:

02/02/2026

Document Number:

720800253

FIELD INSPECTION FORM

Loc ID 438327 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason	303-330-1921	jason@strachanexploration.com	
Reed, Shawn		Shawn@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438322	WELL	PR	04/01/2025	OW	123-39927	Loomis 2-3H	PR
438324	WELL	PR	12/31/2014	OW	123-39929	Loomis 2-6H	PR
438325	WELL	PR	05/01/2023	OW	123-39930	Loomis 2-1H	PR

General Comment:

[This is a Well Pad and Tank Battery Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signs still show previous Operator's Info; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/13/2026
Type	BATTERY		
Comment:	Signs still show previous Operator's Info; see photos		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	03/13/2026
Type	CONTAINERS		
Comment:	South Chemical Tank inside Tank Berm and Chemical Tank at Gas Meters- Labels have faded no longer visible		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/13/2026
Type	TANK LABELS/PLACARDS		
Comment:	Tanks - 9457, 9548 and 9459 - Content and Capacity Labels have faded no longer visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/13/2026

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Gas Meters; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	02/13/2026
Type	UNUSED EQUIPMENT		
Comment:	Unused Wellhead parts and downhole tools at all three Pumping Units		
Corrective Action:	Comply with Rule 606	Date:	02/13/2026
Type	OTHER		
Comment:	Stained Soil at all three Wellheads and Pumping Units; see photos		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."		Date: 02/13/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	Equipment has not changed from previous FIR		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:	Flare has been removed and Sales Line Compressor has been installed. New Operator has closed all valves to Flare line		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 438322 Type: WELL API Number: 123-39927 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438324 Type: WELL API Number: 123-39929 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438325 Type: WELL API Number: 123-39930 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
	petrie	01/30/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720800256	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7435632