

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

02/03/2026

Document Number:

713401188

FIELD INSPECTION FORM

Loc ID 314247 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Saint, John		jsaint@scoutep.com	
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Beasley, Nolan		nolan.beasley@state.co.us	
Toews, Wesley		wtoews@blm.gov	
Sanford, Anita		anita.sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228119	WELL	IJ	02/01/2017	ERIW	103-01037	CARNEY C T 15-35	AC

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

[UIC-5 yr MIT. Please refer to Form 42 Document #404502627](#)

Location

Lease Road:

	Type Access		
comment:	Access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	970-675-3700/911		
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

		#		corrective date
Type: Other		# 1		
Comment:	Pump truck			
Corrective Action:				Date:
Type: Deadman # & Marked		# 4		
Comment:				
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge			
Corrective Action:				Date:
Type: Ancillary equipment		# 1		
Comment:	WAG skid			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 228119 Type: WELL API Number: 103-01037 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WEBR

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 02/18/2021

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 1650 Csg psi: 2005 BH psi: 0

Insp. Status: _____

Comment: UIC-5 yr MIT.
Please refer to Form 42 Document #404502627
Pressure casing to 2005 psi. Hold for 15 min. Final pressure 2005 psi. 0 psi loss.
Test witnessed by ECMC using chart on test truck & gauge.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						Light compaction
		Compaction				Light compaction
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 01/22/2026 at approximately 10:42 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit for a UIC-5 yr MIT at SCOUT ENERGY MANAGEMENT LLC CARNEY 15-35 PAD at Location ID #314247 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed UIC-5 yr MIT operations.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	02/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401215	71340188 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7436227