

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Impacted waters and inadequate storage of supplies

Impacted waters and inadequate storage of supplies

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Impacted waters and inadequate storage of supplies

Impacted waters and inadequate storage of supplies

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Impacted waters and inadequate storage of supplies

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Stained soil observed upstream



Stained soil observed upstream



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Stained soil observed upstream

Stained soil observed upstream

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Stained soil observed upstream

Stained soil observed upstream

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Presumed release point location excavation

Presumed release point location excavation. Oily sheen observed on water within excavation.

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Waste stockpile. Inadequate stockpile management

Waste stockpile. Inadequate stockpile management

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inadequate stockpile management

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inadequate absorbent mats

Inadequate absorbent mats



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inadequate booms

Inadequate booms

Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917



Inspection Photos
Location Name: Facility 5 Gas Line
Spill ID: 492917

