

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/03/2026

Document Number:

715801892

**FIELD INSPECTION FORM**

Loc ID 321459 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272632	WELL	PR	10/13/2025	GW	013-06509	VICKLUND G 32-2	WK

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Location entrance signs are adequate.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>	Date:	
Corrective Action:	<input style="width: 95%;" type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Straw bale along the eastern side in the round.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 272632 Type: WELL API Number: 013-06509 Status: PR Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: AXIS

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 1001'-701'

Cement Volume (sx): 76

Good Return During Job: YES

Cement Type: III

Comment: Arrived on location @ 1040 hrs, Axis Cement crew on location & RU. Safety meeting/JSA, Pressure test lines, batch up/mix 76 sks of type III cement to 15.8 lbs & pump & set plug from 1001 ft.(bottom) to 701 ft.(top). Cement crew clean up RDMO.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/28/2025

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: After Cement job WO rig crew TOO H with tubing & LD on the trailer & standing back in the derrick. WOC.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
This Field Inspection is due to a form 42 (PA) doc # 404509095 & form 42 (MIRU) doc# 404509111. Arrived on location @ 1040 hrs, Axis Cement crew on location & RU. Safety meeting/JSA, Pressure test lines, batch up/mix 76 sks of type III cement to 14.5 lbs. Pump & set plug from 1001 ft.(bottom) to 701 ft.(top). Cement crew clean up RDMO, WO rig crew TOOH with tubing LD on trailer & standing back in the derrick. WOC. Weather: Cloudy Temperature: 39* Location: Dry.	revasr	02/03/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715801893	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7437470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7437470</a>