


Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



01 – Well Sign posted on side of meter run shed. Note that 24 hour and emergency contact numbers are getting very difficult to read.

## Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



**02. Well head and well pad area. Note that dead vegetative material from last season is accumulated. The well production area and lease road appear to be composed of native sand and not gravel, which is mostly buried or washed away.**

## Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



### 3. Wellhead.

## Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



**4: Steel PBV Tank. The tank has an expanded metal top. It appears to contain produced water, but there is no sign to indicate contents or volume.**

## Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



**5. Heated horizontal separator. Note that there is dead vegetative debris accumulating near the separator.**

## Inspection Photos

Location Name: Logos Operating LLC. – Northwest Cedar Hill 32-10API # 05-067-05010

Inspector Name: Jamie Blair. Inspection Date: 02/02/2026

Inspection Doc #: 721100095



6. Meter run shed. The calibration card was present inside the structure. Dated 1/20/2026. There is no latch on the door, which swings freely in the wind.