

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2026

Submitted Date:

01/28/2026

Document Number:

701104470

FIELD INSPECTION FORM

Loc ID 335773 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270316	WELL	PR	04/01/2019	GW	045-09525	CHEVRON 23C-17D	EG
270317	WELL	PR	03/01/2019	GW	045-09526	CHEVRON 23A-17D	EG
270318	WELL	SI	08/01/2022	GW	045-09527	CHEVRON 22C-17D	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Production tank replace since 12/09/2026 inspection doc # 701104381 that note damage to old tank.
Visible external corrosion of valve and inlet line for 23A-17D
Maintain mechanical integrity of equipment. Rule 608.e
CA Date 2/13/2026

Location

Lease Road:

Type	Access				
comment:					
Corrective Action				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Type	BATTERY				
Comment:					
Corrective Action:				Date:	
Type	TANK LABELS/PLACARDS				
Comment:	Tank has been replaced and replacement tank needs to be labeled.				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	911				
Corrective Action:				Date:	_____

Good Housekeeping:

Type	TRASH				
Comment:					
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					

Equipment:

					corrective date
Type:	Horizontal Heated Separator	# 3			
Comment:	Visible external corroison of valve and inlet line for 23A-17D				
Corrective Action:	Maintain mechanical integrity of equipment. Rule 608.e			Date:	02/13/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	300 BBLs	STEEL AST		,
Comment:	Tank replaced				
Corrective Action:				Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Liner replaced				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 270316 Type: WELL API Number: 045-09525 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270317 Type: WELL API Number: 045-09526 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270318 Type: WELL API Number: 045-09527 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404522388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7429529
701104471	Flowline integrity inspection 701104470 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7429528