

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/04/2026

Document Number:

719700433

FIELD INSPECTION FORM

Loc ID 331940 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431501	WELL	SI	01/01/2025	OW	123-36627	State Peterson 2D-20H	SI
431502	WELL	SI	11/01/2025	OW	123-36628	State Peterson 2F-20H	SI
431503	WELL	SI	01/01/2025	OW	123-36629	State Peterson 2E-20H	SI
431504	WELL	SI	01/01/2025	OW	123-36630	State Peterson 2A-20H	SI
431505	WELL	SI	01/01/2025	OW	123-36631	State Peterson 2C-20H	SI
431506	WELL	SI	01/01/2025	OW	123-36632	State Peterson 2B-20H	SI

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Wellsite(s): 6	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	Posted.	
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Wellsite(s): 6 Iron mesh panel.	
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 6		
	Comment:	Wellsite(s): 6	
Corrective Action:			Date:
Type: Bradenhead	# 6		
	Comment:	Wellsite(s): 6 Appears plumbed to surface.	
Corrective Action:			Date:

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.389600,-104.464913	
	Comment:	Centralized Battery serves 1 Location ID. (331940). (Well(s): 6: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (484298).				
Corrective Action:						Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 431501 Type: WELL API Number: 123-36627 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 11/2024.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431502 Type: WELL API Number: 123-36628 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 10/2025.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431503 Type: WELL API Number: 123-36629 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 11/2024.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431504 Type: WELL API Number: 123-36630 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 11/2024.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431505 Type: WELL API Number: 123-36631 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 11/2024.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 04/09/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 48 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431506 Type: WELL API Number: 123-36632 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
ECMC records last prod: 11/2024.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/09/2025

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 02/03/2026 at approximately 14:47 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: CRESTONE PEAK RESOURCES OPERATING LLC Location Name: State Peterson/20H-D563 Location ID: 331940 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Refer to attached audit photo(s). Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 6: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	02/05/2026

<p>This is a WELL audit. Well(s): 6: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID. (331940). (Well(s): 6: Shut-In SI).</p> <p>Centralized Battery Formerly served 1 well on Location 331940. (Well(s): 1: Plugged & Abandoned PA).</p> <p>Centralized Battery Formerly served 4 Location IDs. (305076, 309941, 309942, 332002). (Well(s): 4: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (484298).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700433 and/or Location ID #331940 for SI Well(s) info. B.) Field Audit Report doc. #719700435 and/or Location ID #331940 for PA Well(s) info. C.) Field Audit Report doc. #719700437 and/or Location ID #305076 for PA Well(s) info. D.) Field Audit Report doc. #719700439 and/or Location ID #309941 for PA Well(s) info. E.) Field Audit Report doc. #719700441 and/or Location ID #332002 for PA Well(s) info. F.) Field Audit Report doc. #719700443 and/or Facility ID #484298 for Battery / Facility, Equipment info.</p>	<p>evinsb</p>	<p>02/04/2026</p>
---	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700434	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7439837