

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/05/2026

Document Number:

694500815

FIELD INSPECTION FORM

Loc ID 312982 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|------------------------------------|---------|
| , | | argaliexplorationcompany@gmail.com | |
| hinaman, gary | (970) 675-8257 | hinaman@lexry.com | |
| Jackson, Ben | | ben.jackson@state.co.us | |
| Ramsey, Scott | | scott.ramsey@state.co.us | |
| Fischer, Alex | | alex.fischer@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 112097 | PIT | | | | - | MCWILLIAMS 4-31 | EI |
| 116597 | PIT | AC | | | - | MCWILLIAMS 4-31 | EI |
| 223159 | WELL | PR | 09/01/2018 | GW | 081-06521 | MCWILLIAMS 4-31 | EI |

General Comment:

On 2/3/2026, ECMC staff Kris Neidel inspected the MC Williams #4-31 location (05-081-06521). Corrective Actions from previous inspections that have not been addressed are still applicable. Weather was cloudy, ~35°F. Observations include: no sign at the lease and public road intersection; well appeared SI; pit was fenced with no fluid or apparent hydrocarbons observed. Corrective Actions: Comply with signage Rule 406.d. Pit water sampling per Rule 909.j appears to not have been submitted to ECMC; the Operator shall submit all sampling required by Rule 909.j. See attached photos..

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| | | | |
| Type | OTHER | | |
| Comment: | No sign at lease road and the public road. | | |
| Corrective Action: | Comply with sign rule 406.d. | Date: | 02/26/2026 |

Emergency Contact Number:

Comment: 970-629-1906

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 112097 Type: PIT API Number: - Status: _____ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 116597 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 223159 Type: WELL API Number: 081-06521 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 112097 Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment: No Observed engineered liner. Pit water sampling per Rule 909.j appears to have not been submitted to ECMC.

Corrective Action Pit water sampling per Rule 909.j appears unsubmitted to ECMC; the Operator shall submit all sampling required by Rule 909.j

Date: _____

Fencing:

Fencing Type: Other Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Netting Condition:

Comment: No Netting

Corrective Action

Date: _____

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694500816 | photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440656 |