

Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Impacted waters and inadequate mats

Impacted waters and inadequate mats



**Inspection Photos**  
**Location Name: Facility 5 Gas Line**  
**Spill ID: 492917**



**Absorbent mats downstream**



Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Presumed release point location excavation

Presumed release point location excavation. Oily sheen observed on water within excavation.

**Inspection Photos**  
**Location Name: Facility 5 Gas Line**  
**Spill ID: 492917**



**Stained oily soil. Location of submitted sample**

**Stained oily soil. Location of submitted sample**

Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Stained oily soil. Location of submitted sample



Stained oily soil. Location of submitted sample

**Inspection Photos**  
**Location Name: Facility 5 Gas Line**  
**Spill ID: 492917**



**Stockpile**

**Impacted soil beneath hauled off soil stockpile**

Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Impacted soil beneath hauled off soil stockpile

**Inspection Photos**  
**Location Name: Facility 5 Gas Line**  
**Spill ID: 492917**



**Impacted oily stockpile**



**Possible sheen location just beyond boom**

Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Possible sheen location just beyond boom

Possible sheen



Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Possible sheen

Inspection Photos  
Location Name: Facility 5 Gas Line  
Spill ID: 492917



Last boom



Possible raptor from nearby nest

**Inspection Photos**  
**Location Name: Facility 5 Gas Line**  
**Spill ID: 492917**



**Possible raptor from nearby nest**

