

Inspection Photos

Loc: 324881

Operator: RAMPIKE RESOURCES LTD

Inspection Date: 2/2/2026

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the former access road. The vegetation is not establishing and disturbed soils need to be reseeded.



Inspection Photos



Photo 2. Drone aerial photo facing north. The road has not revegetated and must be reclaimed.



Inspection Photos



Photo 3. Drone aerial photo shows bare soils along the road that have not revegetated.



Inspection Photos



Photo 4. Drone aerial photo facing down toward the abandoned wellsite. There are areas bare of vegetation that need to be reseeded.

