

Inspection Photos

Company: Simcoe LLC. – Well: Opal Lechner

API # 05-067-07336

Inspector Name: James Blair. Inspection Date: 02/04/2026

Inspection Doc #:721100104



1. Well sign. Sign was laying face down upon arrival. Should be secured in upright fashion in visible location.

Inspection Photos  
Company: Simcoe LLC. – Well: Opal Lechner  
API # 05-067-07336  
Inspector Name: James Blair. Inspection Date: 02/04/2026  
Inspection Doc #:721100104



2. Direct pump controller.

Inspection Photos  
Company: Simcoe LLC. – Well: Opal Lechner  
API # 05-067-07336  
Inspector Name: James Blair. Inspection Date: 02/04/2026  
Inspection Doc #:721100104



3. Meter run structure.

Inspection Photos  
Company: Simcoe LLC. – Well: Opal Lechner  
API # 05-067-07336  
Inspector Name: James Blair. Inspection Date: 02/04/2026  
Inspection Doc #:721100104



4. Telemetry.

Inspection Photos

Company: Simcoe LLC. – Well: Opal Lechner

API # 05-067-07336

Inspector Name: James Blair. Inspection Date: 02/04/2026

Inspection Doc #:721100104



5. Pumpjack and electric prime mover behind cattle panel fence.


Inspection Photos  
Company: Simcoe LLC. – Well: Opal Lechner  
API # 05-067-07336  
Inspector Name: James Blair. Inspection Date: 02/04/2026  
Inspection Doc #:721100104



Feb 4, 2026 at 3:53:30 PM  
+37.136164 -107.764449  
335° NW  
La Plata County  
Energy & Carbon Management Commission

6. Wellhead. Note oil stain on ground (outlined in yellow) and dead vegetative debris (arrow). View looking north. Staining appears to be from excessive rod-oiler lubrication.

Inspection Photos  
Company: Simcoe LLC. – Well: Opal Lechner  
API # 05-067-07336  
Inspector Name: James Blair. Inspection Date: 02/04/2026  
Inspection Doc #:721100104



7. Wellhead. Note oil stain on ground (outlined in yellow) and dead vegetative debris (arrow). View looking south.

Inspection Photos

Location Name: Mach Resrouces (formerly Simcoe). – Well Name Opal Lechner

API # 05-067-07336

Inspector Name: James Blair. Inspection Date: 02/04/2026

Inspection Doc #:721100104



8. Pumpjack and wellhead. Dead vegetative debris near wellhead.