




9-10N-46W
water wells in area



Called Steve James 9/9
requested DIL across surface casing shoe
if available. COGCC does not have it.
to determine if ~~the~~ additional cementing
requirements needed if production casing
is set. 9/13/94

DIL of upper hole could not be found

per
Steve
James