

Inspection Photos
Location: King Pyles 1
Location ID: 384246
API # 05-061-06017



Photo 1 – Fenced area north looking south

Photo 2 – Fenced area north looking south

Inspection Photos
Location: King Pyles 1
Location ID: 384246
API # 05-061-06017



Photo 3 – Fencing not secured

Photo 4 – Bare area

Inspection Photos
Location: King Pyles 1
Location ID: 384246
API # 05-061-06017



Photo 5 – Area with red piping, subsidence

Photo 6 – Area with red piping, subsidence

Inspection Photos
Location: King Pyles 1
Location ID: 384246
API # 05-061-06017



Photo 7 – Valve can, light vegetation

Photo 8 – Fenced Area light vegetation