

Inspection Photos
Location: Dawson Unit 1
Location ID: 384227
API # 05-061-05142

Facility Name/ Number	
DAWSON UNIT 1	
DAWSON UNIT-619S45W 4SWSE	
DAWSON UNIT 1	



Photo 1 – Well information

Photo 2 – Distressed Vegetation. Impacted soils

Inspection Photos
Location: Dawson Unit 1
Location ID: 384227
API # 05-061-05142



Photo 3 – Distressed Vegetation. Impacted soils

Photo 4 – Distressed Vegetation. Impacted soils

Inspection Photos
Location: Dawson Unit 1
Location ID: 384227
API # 05-061-05142



Photo 5 – Distressed Vegetation. Impacted Soils

Photo 6 – Impacted soils, remnants of oilfield equipment.

Inspection Photos
Location: Dawson Unit 1
Location ID: 384227
API # 05-061-05142



Photo 7 – Flowline Valve Box, area in distance is sandy material identified in Reclamation Inspection Document no. 713600600

Photo 8 – Area of disturbance, Sandy Soils