

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/05/2026

Document Number:

710500699

FIELD INSPECTION FORM

Loc ID 384227 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Coleman, Chris		chris.coleman@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212634	WELL	PA	09/10/2000	OW	061-05142	DAWSON UNIT 1	EI

General Comment:

This is an Environmental Inspection for the Dawson Unit 1 Plugged and Abandon, well location located in Kiowa County, Colorado.

This is a follow up to Reclamation Inspection(s), no. 713600600, 713600280, 690203948 and Environmental Inspection no. 700600420.

Location ID: 384227
API #: 05-061-05142
Pit Facility ID 115304
Well plug date: 9/10/2000.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: At the time of inspection, remnants of oilfield equipment were observed within the fenced boundary of the well location.

Comply with Rule 1004.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

Crude Oil

Comment: At the time of inspection, impacted soils were observed within the fenced boundary of the historical well location. There is evidence of a prior excavation within the boundary however impacts to soils remain.

Reclamation Inspection document no. 713600600 comment states: There has been excavation and removal of impacted soils from the flowline area near the location. It is unknown if there was more than 10 cubic yards of impacted soil removed and Operator has not submitted Form 19 spill report. This will be referred to EPS Staff.

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 02/12/2026

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: There is an electrical fence surrounding the location to keep livestock from entering the location

Maintain Fencing and Comply with the fencing requirements per the 1002a rules

Corrective Action:

Date:

Equipment:

corrective date

Type: Flow Line

#

Comment: Reclamation Inspection document no. 713600600 identifies: There is an abandoned flowline cellar that remains.

Corrective Action: Operator shall provide additional details for the flowline equipment, Operator shall identify if the equipment is abandoned or active. If the equipment is abandoned the Operator shall comply with Rule 1105. Flowline Abandonment.

Date: 03/12/2026

Venting:

Yes/No

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 212634 Type: WELL API Number: 061-05142 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs), and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	02/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500702	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441947