

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2026

Submitted Date:

02/01/2026

Document Number:

713401207

**FIELD INSPECTION FORM**

Loc ID 314651 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229197	WELL	PR	06/25/1961	GW	103-06284	DOUGLAS CREEK UNIT 7	PR

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-693-6021/911		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	30 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 229197 Type: WELL API Number: 103-06284 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
Berms						
		Compaction				Light compaction
Ditches						
		Ditches				
		Berms				
Other	Fail					Failure to minimize erosion on cut slope

**Comment:** 1. Failure to minimize erosion & transport of sediment/insufficient BMP's. Erosion & transport of sediment on cut slope and sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability.

Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

**Corrective Action:** Comply with CECMC rule 1002

**Date:** 08/20/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection/Audit Report Summary</b></p> <p>On 01/14/2026 at approximately 11:18 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD at Location ID #314651 in Rio Blanco County, Colorado.</p> <p>Please refer to inspection/audit 713400953 conducted on 07/29/2025 &amp; inspection 713401086 conducted on 09/17/2025, Battery signage corrective action has been completed. Failure to minimize erosion &amp; transport of sediment/insufficient BMP's. Erosion &amp; transport of sediment on cut slope and sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability and has not been resolved and corrective action date remains the same.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Stormwater - Failure to minimize erosion &amp; transport of sediment/insufficient BMP's. Erosion &amp; transport of sediment on cut slope and sediment is migrating onto location near tank battery, the cut slope has experienced progressive erosion and is now actively sloughing, resulting in slope instability with a CA date of 08/20/2025</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	02/01/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404527724	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434122</a>
713401208	713401207 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7434121</a>