

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2026

Submitted Date:

02/02/2026

Document Number:

720800262

FIELD INSPECTION FORM

Loc ID 429227 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason	303-330-1921	jason@strachanexploration.com	
Reed, Shawn		Shawn@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429228	WELL	PR	09/12/2014	OW	123-35755	GREEN 1-10	PR

General Comment:

[This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

Location

Overall Good:

Signs/Marker:

	Type	WELLHEAD
	Comment:	Adequate
Corrective Action:		Date:

Emergency Contact Number:

Comment:	<input type="text"/>	Date:
Corrective Action:	<input type="text"/>	<input type="text"/>

Good Housekeeping:

Type	OTHER	
	Comment:	Stained Soil at Pumping Unit; see photos
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date: 02/13/2026

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 429228 Type: WELL API Number: 123-35755 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404529167	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7435645
720800263	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7435636