

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1735 Entrance to location



Photo # 1736 Entrance to location

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1789 Operator emergency Contact Number is not in service




Photo # 1740 Location

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1741 Location



Photo # 1748 Wellhead

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026




Photo # 1788 Location



Photo # 1819 NW corner of location

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1821 NE corner of location



Photo # 1822 SW corner of location

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1823 SE corner of location



Photo # 1749 Bradenhead inaccessible

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1754 Staining



Photo # 1770 Staining

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1772 Staining/Weeds/undesirable plant species presents a potential fire hazard



Photo # 1774 Staining/Weeds/undesirable plant species presents a potential fire hazard

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1776 Possible flowline lacks integrity



Photo # 1779 Staining/Weeds/undesirable plant species presents a potential fire hazard

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1784 Staining/Weeds/undesirable plant species presents a potential fire hazard



Photo # 1785 Staining/Weeds/undesirable plant species presents a potential fire hazard

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1800 Staining/Weeds/undesirable plant species presents a potential fire hazard



Photo # 1803 Staining

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1805 Staining



Photo # 1808 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1810 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 1813 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1794 Weeds/undesirable plant species presents a potential fire hazard



Photo # 1795 Weeds/undesirable plant species presents a potential fire hazard

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1796 Weeds/undesirable plant species presents a potential fire hazard



Photo # 1798 Weeds/undesirable plant species presents a potential fire hazard

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1799 Weeds/undesirable plant species presents a potential fire hazard



Photo # 1827 Unused flowlines lack lockout tagout (OOSLAT)

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1829 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 1830 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1790 Production tank labels not legible & lack required labeling/not in compliance with CECMC rules




Photo # 1791 Production tank labels not legible & lack required labeling/not in compliance with CECMC rules

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1815 Unused unload line near tank battery not necessary for use on location



Photo # 1816 Unused unload line near tank battery not necessary for use on location

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1825 Debris



Photo # 1826 Debris

Inspection/Audit Photos

Location: GRAND VALLEY RESOURCES INC ANDERSON-GOVERNMENT #17-1 PAD

Location ID: 316695

Date: 02/5/2026



Photo # 1838 Unmarked deadman