

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2026

Submitted Date:

02/09/2026

Document Number:

717300746

FIELD INSPECTION FORM

Loc ID 336477 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261856	WELL	PA	07/11/2025	GW	123-20652	DIER 13-8	PA
470440	Location	AC			-	DIER-62N67W 8NWSW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 261856 Type: WELL API Number: 123-20652 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 470440 Type: Location API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Dier 13-8); ECMC form 42 notice of start of plugging operations doc #404216471 received on 05/23/2025. The facility/ tank battery has been decommissioned; tanks and equipment and on location flowlines removed. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	02/09/2026
As outlined on ECMC form 19 spill report Doc #404521684 received on 01/28/2026: During decommissioning activities at the Dier 13 14-8, historical impacts were identified.	maclarej	02/09/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300748	Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442908
717300749	PA well and facility; No FL's/ Risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442909