

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2026

Submitted Date:

02/09/2026

Document Number:

719200799

FIELD INSPECTION FORM

Loc ID 334927 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264882	WELL	PA	07/22/2021	GW	045-08959	COUEY 5-14B (N5A)	RI
265838	WELL	PA	07/22/2021	GW	045-09067	COUEY 5-10C (N5A)	RI
265841	WELL	PA	07/22/2021	GW	045-09070	COUEY 5-15A (N5A)	RI
334927	LOCATION	CL			-	COUEY-67S92W 5SESW	RI

General Comment:

On 02/06/2026, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at QB Energy Operating LLC's COUEY-67S92W/5SESW location in Garfield County, Colorado.

The location is within CPW High Priority Habitat: Elk Severe Winter Range, Elk Winter Concentration Area, Mule Deer Winter Concentration Area, Mule Deer Severe Winter Range.

Refer to the Reclamation and ECMC Comments sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Inspected Facilities

Facility ID: 264882 Type: WELL API Number: 045-08959 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 265838 Type: WELL API Number: 045-09067 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 265841 Type: WELL API Number: 045-09070 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 334927 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present **Fail** Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

ECMC Comments

Comment	User	Date
<p>Reclamation Comments: This location shares a main access road with active location #334963. The southeastern access road that branches off from the main access road and leads to this location has been reclaimed. Facilities have received closure via Form 27's. All wells have been cut/capped below grade and recontoured.</p> <p>This inspection was conducted during the dormant season. The northern and eastern portions of the location appear to be progressing towards 1004 reclamation requirements and desirable, perennial and uniform vegetation (such as rubber rabbitbrush, fourwing saltbush and perennial grasses) is present and appears to be progressing towards eighty (80) percent vegetative cover. Inspection #696205122 noted undesirable plants throughout the location in 2023.</p> <p>The southern and southeastern portions of the location do not appear to be progressing towards 1004 requirements; these portions are predominantly bare or populated by prickly Russian thistle, an undesirable annual plant species. Perennial, desirable and uniform vegetation is not evident. Hydroseeding efforts appear to have failed in these portions of the location; inspector did not observe germination within these areas.</p> <p>A follow-up inspection will be conducted during the 2026 growing season to determine progression towards 1004 reclamation standards. Continue to monitor/manage weeds until site receives a passing final reclamation inspection. Additional reclamation efforts may be required in the future.</p>	gaaschee	02/09/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719200800	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7443952