

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2026

Submitted Date:

02/03/2026

Document Number:

721100095

FIELD INSPECTION FORM

Loc ID 324973 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
		regulatory@logosresourcesllc.com	All Inspections 8/2/2021

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213754	WELL	PR	10/11/1955	GW	067-05010	NORTHWEST CEDAR HILL 32-10 2-20	PR

General Comment:

On Monday, February 2, 2026 James Blair performed a compliance audit and inspection. Any corrective actions from previous inspections not addressed in this report remain in effect. Photos are included as an attachment to this report.

Location			
Lease Road:			
Type	Access		
comment:	2-track native surface. Photo 2.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	photos 2, 4.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	PBV tank with expanded metal top lacks sign. No indication of contents or volume, etc. Photo 4.		
Corrective Action:	Install sign to comply with 605.e.		Date: 04/07/2026
Emergency Contact Number:			
Comment:	24 hr: 855-589-6220. Emergency: 911. Observation - becoming hard to read. Photo 1.		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Wellhead area is filled with sand from flooding or wind.		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Dead vegetative debris from previous year near heated separator and other equipment. Photos 2, 3, 5.		
Corrective Action:	Remove all dead vegetative debris a minimum of 25 feet from wellhead, tank and separator to comply with rule 610.k		Date: 02/06/2026
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	T-post and 4" wire mesh.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	steel pipe barricade.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 2		corrective date

Comment: telemetry and solar.		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment: Photos 4, 5.		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: 1/20/2026 calibration date. Photo 6.		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears to be accessible via PVC pipes, but sediment has washed in and burried fittings. Photo 2.		
Corrective Action:		Date:
Type: Flow Line	# 4	
Comment: Same as observed in inspection 687905556.		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment: on separator stack		
Corrective Action:		Date:
Type: Deadman # & Marked	# 1	
Comment: Only one observed.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.002240,-107.962177
Comment: Volume, contents and other information unknown. No sign. Est less than 100 bbl. See signs section for CA. Photo 4.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 213754 Type: WELL API Number: 067-05010 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			
Berms	Pass	Other	Pass			

Comment: [Access road and pad made of native sandy soil. Very sandy, erodable.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
The tank needs a sign. Remove dead vegetative debris.	blairj1	02/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404531351	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7437725
721100100	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7437723