

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2026

Submitted Date:

02/10/2026

Document Number:

701104483

FIELD INSPECTION FORM

Loc ID 334733 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|--------------------------------|------------------------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Energy, QB | | ecmc.inspections@qb-energy.com | QB Inspection mail box |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 290042 | WELL | SI | 11/01/2023 | GW | 045-13962 | MAP LLC 11-13 (PK11) | EG |
| 290043 | WELL | PR | 05/01/2025 | GW | 045-13961 | MAP LLC 11-14 (PK11) | EG |
| 292399 | WELL | PR | 05/01/2025 | GW | 045-14721 | MAP LLC 11-11BB (PK11) | EG |
| 292400 | WELL | PR | 05/01/2025 | GW | 045-14720 | MAP LLC 11-13BB (PK11) | EG |
| 292488 | WELL | SI | 11/01/2023 | GW | 045-14729 | MAP LLC 11-12BB (PK11) | EG |

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Tank paint is peeling and fadding. Rust developing in strached areas and under label(s). Also man hatches around bolted seals. Monitor, inspect, and repair rust and paint for integrity.
Tank label is damaged with tank rusted behind it.
Install sign to comply with Rule 605.h.
CA Date 03/13/2026

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|---|--|------------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank label is damaged with tank rusted behind it. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | | Date: 03/13/2026 |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|---|--|-----------------|
| Equipment: | | | corrective date |
| Type: | # | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | | | |
|-------------------------|---|----------|-----------|---------|--------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | Tank paint is peeling and fading. Rust developing in strached areas and under label (s). Also man hatches around bolted seals. Monitor, inspect, and repair rust and paint for integrity. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | |
|------------------|------------|--|--|
| Condition | Inadequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |

| | |
|--------------------|--|
| Other (Type) _____ | |
|--------------------|--|

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 290042 Type: WELL API Number: 045-13962 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 290043 Type: WELL API Number: 045-13961 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292399 Type: WELL API Number: 045-14721 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292400 Type: WELL API Number: 045-14720 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292488 Type: WELL API Number: 045-14729 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 701104484 | Flowline integrity inspection 701104483 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7444937 |