

Inspection Photos  
Location Name: Facility 5 @ 42 Pan Am E  
Spill ID: 488117



Excavation. Torn fencing, weeds

Excavation. Torn fencing, weeds

Inspection Photos  
Location Name: Facility 5 @ 42 Pan Am E  
Spill ID: 488117



Excavation. Torn fencing, weeds

Stockpile with no stormwater BMPs

Inspection Photos  
Location Name: Facility 5 @ 42 Pan Am E  
Spill ID: 488117



**Excavation. Torn fencing, weeds. Stockpile with no stormwater BMPs**