

INSPECTION PHOTOS

Well: Golden Eagle 34-13

API #: 05-071-09478

INSPECTION DOC #: 716301955

Operator: OGRIS OPERATING LLC 10758

Inspection date: 2/10/2026

County: Las Animas

BENCHMARK
EQUIPMENT
&
TANK



719-497-0446
or EMERGENCY 911-

WDID 1912564
PERMIT 74292

GOLDEN EAGLE 34-13
SW/SW 34-33S-67W

NAD 83

L AT. 37.122739

Network: Feb 10, 2026 at 12:12:36 PM MST
Local: Feb 10, 2026 at 12:12:36 PM MST
+37.122575, -104.883016
Las Animas County

PHOTO 2: WELL SIGN



Network:Feb 10, 2026 at 11:44:13 AM MST
Local:Feb 10, 2026 at 11:44:13 AM MST
+37.125294,-104.886441
Las Animas County

PHOTO 3: LOCATION.



PHOTO 4: area of impacted soil near wellhead appears to be from leaking hydraulic hoses. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



Network: Feb 10, 2026 at 12:13:55 PM
Local: Feb 10, 2026 at 12:13:55 PM
+37.122761, -104.8
Las Animas C
Altitude: 2333.6
Speed: 0.



PHOTO 5: area of impacted soil near prime mover skid appears to be used oil leaking out of exhaust. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



Network: Feb 10, 2026 at 12:14:12 PM MST
Local: Feb 10, 2026 at 12:14:12 PM MST
+37.122761, -104.883025
Las Animas County

PHOTO 6: area of impacted soil near prime mover skid appears to be used oil leaking out of exhaust. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 7: area of impacted soil near compressor appears to be from leaking equipment over an extended period of time. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. ca date 2/23/2026.



PHOTO 8: area of impacted soil near compressor appears to be from leaking equipment over an extended period of time. **Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 102,.(2).D. ca date 2/23/2026.**



PHOTO 8: area of impacted soil near compressor appears to be from leaking equipment over an extended period of time. **Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. ca date 2/23/2026.**



Network:Feb 10, 2026 at 12:15:58 PM MST
Local:Feb 10, 2026 at 12:15:58 PM MST
+37.122601,-104.883091
Las Animas County

PHOTO 10 trash on location. Remove all trash on and around location per rule 606. ca date 2/23/2026.



PHOTO 11: oily waste in prime mover engine skid without wildlife protections in place. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. this equipment is leaking so bad in should be taken out of service until leaks are repaired. Ca date 2/11/2026.