

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/10/2026

Document Number:

716301959

**FIELD INSPECTION FORM**

Loc ID 309511 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	<a href="#">All Inspections</a>
B WARD, GIENA		gward@ogrisop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297298	WELL	PR	01/27/2009	CBM	071-09633	APACHE CANYON 04-01	PR

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5: Area of impacted soil near wellhead appears to be from leaking hydraulic hose. PHOTO 6 & 7: Area of impacted soil near prime mover engine skid. PHOTO 8: Area of impacted soil near compressor skid.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.	Date:	02/23/2026
Type	TRASH		
Comment:	PHOTO 9 & 10: trash on location near compressor skid.		
Corrective Action:	Remove all trash from on and around location per rule 606.	Date:	02/23/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	25 BBL PRODUCED WATER TANK.		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	FORM 4 VACUUM SUNDRY DOC #1897302		

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 297298 Type: WELL API Number: 071-09633 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/24/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: [PHOTO 11: OILY WASTE IN COMPRESSOR SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS.](#)  
[PHOTO 12: OILY WASTE IN PRIME MOVE ENGINE SKID WITHOUT WILDLIFE PROTECTION SCREENS OR COVERS.](#)

Corrective Action: [DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002.\(2\).D & 1002.f.\(2\)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. immediate action is required.](#)

Date: 02/11/2026

**Pits:**     NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	300255	1841326	

**ECMC Comments**

Comment	User	Date
<a href="#">ECMC Inspection Report Summary</a> Date: 2/10/2026 Time: 14:36 Operator: Ogris Operating LLC.10758 Location: Apache Canyon 04-01 API# 05-071-09633 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: impacted soils in various points around location, RULE 1002.(2).D. ca date 2/23/2026. trash, rule 606. ca date 2/23/2026. oily waste in skids, RULE 1002.(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. immediate action is required, ca date 2/11/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.	beardslt	02/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301960	insp. photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7445444">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7445444</a>