

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



Location Overview – Photo #02630



Location – Photo #02632

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



Location – Photo #02635



Location – Photo #02633

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



Location – Photo #02631



Wildlife Entry Hazard – Photo #02636

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



Open-Ended Load Line – Photo #02643



Unplugged Line – Photo #02640

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



Insufficient Erosion Controls on Cut Slope – Photo #02639



Cut Slope Erosion Encroaching into Secondary Containment – Photo #02637

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



**Cut Slope Erosion Encroaching into Secondary Containment
– Photo #02638**



**Cut Slope Erosion Encroaching into Secondary Containment
– Photo #02641**

Audit Photos

Location Name: QB ENERGY OPERATING LLC, CHEVRON/O36A 596

Location ID: 335583

Date: 2/5/2026



**Cut Slope Erosion Encroaching into Secondary Containment
– Photo #02642**