

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/04/2026

Document Number:

694500812

**FIELD INSPECTION FORM**

Loc ID 312949 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
hinaman, gary	(970) 675-8257	hinaman@lexry.com	
Ramsey, Scott		scott.ramsey@state.co.us	
,		argaliexplorationcompany@gmail.com	
Fischer, Alex		alex.fischer@state.co.us	
Jackson, Ben		ben.jackson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112096	PIT	AC			-	MCWILLIAMS 2-31	EI
222989	WELL	PR	02/01/2024	GW	081-06351	MC WILLIAMS 2-31	EI

**General Comment:**

On 2/3/2026, ECMC staff Kris Neidel inspected the MC Williams #2-31 location (05-081-06351). Corrective Actions from previous inspections that have not been addressed are still applicable. Weather was cloudy, ~35°F. Observations include: no sign at the lease and public road intersection; well appeared SI; pit was fenced with no fluid or apparent hydrocarbons observed; and an unused tank was present. Corrective Actions: Comply with signage Rule 406.d. Pit water sampling per Rule 909.j appears to not have been submitted to ECMC; the Operator shall submit all sampling required by Rule 909.j. See attached photos.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	No sign at lease road and the public road.		
Corrective Action:	Comply with sign rule 406.d.	Date:	03/25/2026

**Emergency Contact Number:**

Comment: 970-629-1906  
970-629-2614

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 112096 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 222989 Type: WELL API Number: 081-06351 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 112096 Lat: 40.612219 Long: -107.529396

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: Other Liner Condition: Inadequate

Comment: No Observed engineered liner. Pit water sampling per Rule 909.j appears to have not been submitted to ECMC.

Corrective Action

Pit water sampling per Rule 909.j appears unsubmitted to ECMC; the Operator shall submit all sampling required by Rule 909.j

Date: 06/01/2026

**Fencing:**

Fencing Type: Other Fencing Condition: Adequate

Comment:

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: No Netting

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404533386	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7439787">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7439787</a>
694500813	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7439773">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7439773</a>