

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2026

Submitted Date:

02/11/2026

Document Number:

708908454

FIELD INSPECTION FORM

Loc ID 323780 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210787	WELL	PR	10/06/1987	GW	045-06545	PFOST W-26-3	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 210787 Type: WELL API Number: 045-06545 Status: PR Insp. Status: PR

Producing Well

Comment: [WBD submitted 12/01/2025 - FORM 4 SUNDRY document # 404454803](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 02/11/2026 at approximately 12:30 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of TEP ROCKY MOUNTAIN LLC PFOST W-26-3 Location # 323780 in Garfield County Colorado. Please refer to inspection/audit 708907905 conducted on 11/21/2025, previous corrective action has been completed. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to Bald Eagle Roost Site. Location is within Rule 411a Surface Water External Buffer.</p> <p>This is a summary of desktop inspection/audit report.</p>	smelserw	02/11/2026