

**FORM
INSP**
Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/11/2026
Submitted Date:
02/11/2026
Document Number:
697012446

FIELD INSPECTION FORM

Loc ID 319164 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
26 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159626	WELL	PR	11/01/2018	OW	123-40987	BUTTERBALL 36N-10HZ	PR
159643	WELL	PR	02/01/2018	OW	123-40989	BUTTERBALL 16C-10HZ	PR
159646	WELL	PR	04/01/2021	OW	123-40990	BUTTERBALL 38N-10HZ	PR
159649	WELL	PR	12/01/2023	OW	123-40991	BUTTERBALL 37N-10HZ	PR
159671	WELL	PR	02/01/2018	OW	123-40999	BUTTERBALL 15C-10HZ	PR
159672	WELL	PR	02/01/2018	OW	123-41000	BUTTERBALL 34C-11HZ	PR
449471	WELL	PR	11/01/2018	OW	123-44315	BUTTERBALL 24N-34HZ	PR
449476	WELL	PR	12/01/2019	OW	123-44316	BUTTERBALL 40N-34HZ	PR
449477	WELL	PR	02/04/2018	OW	123-44317	BUTTERBALL 24N2-34HZ	PR
449481	WELL	PR	12/01/2019	OW	123-44318	BUTTERBALL 9N-34HZ	PR
449488	WELL	PR	09/01/2021	OW	123-44319	BUTTERBALL 40C-34HZ	PR
449491	WELL	PR	03/01/2025	OW	123-44320	BUTTERBALL 24C-34HZ	PR

General Comment:
[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 12		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical systems		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Tumble weeds on east well pad, see attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	02/27/2026
Type	UNUSED EQUIPMENT		
Comment:	Produced water signs at meter runs, see attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	02/27/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 12		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 3		
Comment:	Electric motors on LACT and supplied air system		
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Automation array, electrical systems, chemical systems in secondary containment, supplied air system, Bradenhead gas combustor, ECD scrubber		
Corrective Action:			Date:
Type: Bradenhead	# 12		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:			Date:
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Western Midstream calibration card is current.		
Corrective Action:			Date:
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	OTHER	STEEL AST		
-----------	---	-------	-----------	--	--

Comment:	286 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		

Comment:	286 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No				
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities										
Facility ID:	159626	Type:	WELL	API Number:	123-40987	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159643	Type:	WELL	API Number:	123-40989	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159646	Type:	WELL	API Number:	123-40990	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159649	Type:	WELL	API Number:	123-40991	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159671	Type:	WELL	API Number:	123-40999	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	159672	Type:	WELL	API Number:	123-41000	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449471	Type:	WELL	API Number:	123-44315	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	449476	Type:	WELL	API Number:	123-44316	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	PR									
Corrective Action:							Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449477 Type: WELL API Number: 123-44317 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449481 Type: WELL API Number: 123-44318 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449488 Type: WELL API Number: 123-44319 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 449491 Type: WELL API Number: 123-44320 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Wednesday 2/11/2026 at approximately 10:00 hours I, Inspector Tom Peterson, conducted an on-site inspection at the KMG Butterball 24N2-34 HZ Pad location #319164 in Weld County, Colorado. While there, I observed debris and unused equipment on the location. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 2/27/2026 A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	02/11/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697012447	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7446953