

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/05/2026

Submitted Date:

02/11/2026

Document Number:

719500884

FIELD INSPECTION FORM

Loc ID 311649 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284981	WELL	PR	02/01/2014	GW	045-12334	N.PARACHUTE WF 13D K25 596	PR
284982	WELL	PR	05/01/2025	GW	045-12331	N.PARACHUTE WF01C K25 596	PR
284983	WELL	PR	05/01/2025	GW	045-12333	N.PARACHUTE WF 14C K25 596	PR
284984	WELL	PR	05/01/2025	GW	045-12332	N.PARACHUTE WF03A K25 596	PR
284985	WELL	PR	06/01/2025	GW	045-12330	N.PARACHUTE WF 04A K25 596	PR
284986	WELL	PR	07/04/2008	GW	045-12329	N.PARACHUTE WF 14B K25 596	PR
284987	WELL	PR	05/01/2025	GW	045-12328	N.PARACHUTE WF05B K25 596	PR
284988	WELL	PR	03/20/2008	GW	045-12327	N.PARACHUTE WF01B K25 596	PR
291477	WELL	SI	05/01/2025	GW	045-14398	N. PARACHUTE WF16D K25596	SI
291478	WELL	PR	05/01/2025	GW	045-14399	N.PARACHUTE WF13B K25 596	PR
291533	WELL	PR	05/01/2025	GW	045-14431	N. PARACHUTE WF13C K25 596	PR
291534	WELL	PR	07/23/2007	GW	045-14430	N.PARACHUTE WF14A K25 596	PR
291535	WELL	PR	07/23/2007	GW	045-14429	N. PARACHUTE WF04C K25 596	PR
291536	WELL	PR	06/01/2025	GW	045-14438	N. PARACHUTE WF04BK25596	PR

291537	WELL	PR	06/01/2025	GW	045-14437	N. PARACHUTE WF05AK25596	PR
291538	WELL	PR	02/01/2022	GW	045-14436	N. PARACHUTE WF01A K25 596	PR
291539	WELL	PR	07/24/2007	GW	045-14432	N. PARACHUTE WF13A K25 596	PR
291540	WELL	PR	05/01/2025	GW	045-14433	N. PARACHUTE WF16C K25 596	PR
291541	WELL	PR	05/01/2025	GW	045-14434	N. PARACHUTE WF16BK25596	PR
291542	WELL	SI	10/01/2021	GW	045-14435	N. PARACHUTE WF16AK25596	SI

General Comment:

This is a field audit of the location, scout card, and related documents.

On 2/5/2026 at approximately 12:30, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, N.PARACHUTE-65S96W/25NESW at Location ID #311649 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.		
Corrective Action:	Comply with CECMC Signage Requirements.	Date:	03/12/2026
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-2615

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Concrete barriers installed at gas meters/lift and ancillary equipment.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bradenhead	# 20		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		

Comment: Gas lift		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 20	
Comment:		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment: Line heaters		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 20	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	80 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				
		Date:		

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities									
Facility ID:	284981	Type:	WELL	API Number:	045-12334	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284982	Type:	WELL	API Number:	045-12331	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284983	Type:	WELL	API Number:	045-12333	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284984	Type:	WELL	API Number:	045-12332	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284985	Type:	WELL	API Number:	045-12330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284986	Type:	WELL	API Number:	045-12329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284987	Type:	WELL	API Number:	045-12328	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284988	Type:	WELL	API Number:	045-12327	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291477 Type: WELL API Number: 045-14398 Status: SI Insp. Status: SI

Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>Last produced April 2025 per production report.</u>		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291478 Type: WELL API Number: 045-14399 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291533 Type: WELL API Number: 045-14431 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291534 Type: WELL API Number: 045-14430 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291535 Type: WELL API Number: 045-14429 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291536 Type: WELL API Number: 045-14438 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291537 Type: WELL API Number: 045-14437 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291538 Type: WELL API Number: 045-14436 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291539 Type: WELL API Number: 045-14432 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291540 Type: WELL API Number: 045-14433 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291541 Type: WELL API Number: 045-14434 Status: PR Insp. Status: PR

Producing Well			
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291542 Type: WELL API Number: 045-14435 Status: SI Insp. Status: SI

Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____		
Comment:	Last produced September 2021 per production report. Well is defined Inactive and is on the Plugging List due 12/31/2029. Last Bradenhead test performed May 2025.		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Culverts				
Gravel						
				Material Handling And Spill Prevention		
		Compaction				
		Check Dams				
		Ditches				
Compaction						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) One sign is posted for all wells on location. Stamped steel tags hung on the wells are missing required information (API number) and are not conspicuously posted.</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	02/11/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719500885	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447340