

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2026

Submitted Date:

02/11/2026

Document Number:

719700449

FIELD INSPECTION FORM

Loc ID 414243 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414239	WELL	SI	08/01/2025	OW	123-30705	WELLS RANCH 44-12	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	OOSLAT applied at separator. *Refer to Emergency Contact Number section below.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Emergency contact number with Company & Well Name NOT posted at wellsite. Refer to Rule 605.d for guidance.		
Corrective Action:	*Post emergency contact number with Company & Well Name at wellsite. Comply with Rule 605.d. (30-days). See photo(s) #1.		Date: 03/16/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.410432,-104.380293
Comment:	Centralized Battery serves 2 Location IDs (414238, 414243). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (484856).				

Corrective Action:	Date:
--------------------	-------

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 414239 Type: WELL API Number: 123-30705 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Prod valves shut.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well, separator.
ECMC records last prod: 03/2024.

Form 5B on file. Approved.
Defined Inactive: 11/11/2024.
Noticed Inactive: 02/25/2025
Form 4 on file. TA date: 05/28/2024. Approved.
DH-RBP.
Form 6A on file. Out-of-Svc Designation.
Date: 10/02/2024. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down. Centralized Battery serves 2 Location IDs (414238, 414243). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (484856). Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700447 and/or Location ID #414238 for TA Well(s) info. B.) Field Audit Report doc. #719700449 and/or Location ID #414243 for TA Well(s) info. C.) Field Audit Report doc. #719700452 and/or Facility ID #484856 for Battery / Facility, Equipment info.	evinsb	02/11/2026
CECMC Audit Report Synopsis: On MON 02/09/2026 at approximately 15:00 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Location Name: WELLS RANCH/44-12 Location ID: 414243 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry. While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down. *CORRECTIVE ACTION ITEM(s): 1 1.) Refer to pg 2, "Signs/Marker" section of this report. Routine audit. *Any Corrective Actions from prior audits that have not been addressed remain applicable.	evinsb	02/11/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700451	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447368