

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/05/2026

Document Number:

694500815

FIELD INSPECTION FORM

Loc ID 312982 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 3975
Name of Operator: ARGALI EXPLORATION COMPANY
Address: PO BOX 416
City: RANGELY State: CO Zip: 81648

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		argaliexplorationcompany@gmail.com	
hinaman, gary	(970) 675-8257	hinaman@lexry.com	
Jackson, Ben		ben.jackson@state.co.us	
Ramsey, Scott		scott.ramsey@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112097	PIT				-	MCWILLIAMS 4-31	EI
116597	PIT	AC			-	MCWILLIAMS 4-31	EI
223159	WELL	PR	09/01/2018	GW	081-06521	MCWILLIAMS 4-31	EI

General Comment:

On 2/3/2026, ECMC staff Kris Neidel inspected the MC Williams #4-31 location (05-081-06521). Corrective Actions from previous inspections that have not been addressed are still applicable. Weather was cloudy, ~35°F. Observations include: no sign at the lease and public road intersection; well appeared SI; pit was fenced with no fluid or apparent hydrocarbons observed. Corrective Actions: Comply with signage Rule 406.d. Pit water sampling per Rule 909.j appears to not have been submitted to ECMC; the Operator shall submit all sampling required by Rule 909.j. See attached photos..

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	No sign at lease road and the public road.		
Corrective Action:	Comply with sign rule 406.d.	Date:	02/26/2026

Emergency Contact Number:

Comment: 970-629-1906

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 112097 Type: PIT API Number: - Status: _____ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 116597 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 223159 Type: WELL API Number: 081-06521 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 112097 Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: **No Observed engineered liner. Pit water sampling per Rule 909.j appears to have not been submitted to ECMC.**

Corrective Action

Pit water sampling per Rule 909.j appears unsubmitted to ECMC; the Operator shall submit all sampling required by Rule 909.j

Date: _____

Fencing:

Fencing Type: Other Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: **No Netting**

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404534505	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440657
694500816	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440656