

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2026

Submitted Date:

02/05/2026

Document Number:

708700147

**FIELD INSPECTION FORM**

Loc ID 326660 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10663  
Name of Operator: ENDURING RESOURCES LLC  
Address: 6300 S SYRACUSE WAY, SUITE 525  
City: CENTENNIAL State: CO Zip: 80111

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	<a href="#">SJB inspections</a>
Walter, Klye		kwalter@enduringresources.com	<a href="#">SJB inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261590	WELL	PR	05/01/2002	CBM	067-08647	WHEELER 13-4	EI

**General Comment:**

[This is an environmental inspection. Photos attached to document site status at the time of inspection.](#)  
[Salt stained soil, salt stained wellhead, and pooled water around wellhead were observed during inspection. See corrective action.](#)

**Inspected Facilities**

Facility ID: 261590 Type: WELL API Number: 067-08647 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Salt staining on wellhead, salt stained soil, pooled water around wellhead indicate a produced water leak from wellhead. No active leak observed during inspection.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 03/05/2026

Reportable: NO GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404533739	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440075">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440075</a>
708700148	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440074</a>