

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2026

Submitted Date:

02/05/2026

Document Number:

720800270

FIELD INSPECTION FORM

Loc ID 431817 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431816	WELL	TA	09/22/2023	OW	123-36799	Shable Federal LB33-78HN	TA
431818	WELL	TA	09/22/2023	OW	123-36800	Shable LB 32-68HN	TA

General Comment:

[This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	TRASH		
Comment:	Varies trash on Location near remaining Tanks; see photos		
Corrective Action:	Comply with Rule 606	Date:	02/20/2026
Type	STORAGE OF SUPL		
Comment:	Unused Coriolis Meters at Gas Line; see photos		
Corrective Action:	Comply with Rule 606	Date:	02/20/2026
Type	STORAGE OF SUPL		
Comment:	Unused Tanks on the West side of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	02/20/2026

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 431816 Type: WELL API Number: 123-36799 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Well appears to have been Plugged and Abandoned per Form6S 404326202 dated 08.026.2025 (In-Process) with a Surface Plug date of 05.28.2025 and a Cut and Cap date of 07.29.2025
 Form 27S - 404457267 dated 12.15.2025 on File as Forth Quarter 2025 update
 All surface equipment has been removed except two Tank and Corialis Meters, Final Reclamation appears to still be on going at the time of this Field Compliance Audit

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431818 Type: WELL API Number: 123-36800 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Well appears to have been Plugged and Abandoned per Form6S 404334408 dated 08.028.2025 (In-Process) with a Surface Plug date of 06.02.2025 and a Cut and Cap date of 07.29.2025
 Form 27S - 404460608 dated 12.16.2025 on File as Forth Quarter 2025 update
 All surface equipment has been removed except two Tank and Corialis Meters, Final Reclamation appears to still be on going at the time of this Field Compliance Audit

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
	petrie	02/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404533877	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440153
720800271	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7440151