

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021




1. GP-20 Well Sign.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



2. GP-21 Well Sign.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



**3. Flow line assembly for GP 20 and GP 21 and telemetry. Pipes on blanked-off flanges have printed labels, however “tags” are absent or have been UV decayed and are broken/illegible.**

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



4. Broken gate valve left on site.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



5. Well pad looking southwest from flow line assembly.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



**6. GP-20 wellhead, flow line and 1000 gallon diethylene glycol/produced water tank. Pump in tank was heard operating during inspection. Secondary containment below tank is adequate.**

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



**7. GP-20 wellhead, flow line and 1000-gallon diethylene glycol/produced water tank. Pump in tank was heard operating during inspection. Secondary containment below tank is adequate. Marked with hazcom placard.**

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



8. Diethylene glycol/produced water tank on skid-mounted secondary containment tank. Solar-array/telemetry. Secondary containment is adequate.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



9. GP-21 wellhead and cellar. Bradenhead is accessible beneath grate. Note rag on top.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



10. Well pad looking east from west end.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



11. Access road.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021




12. Run-on control ditch in cut slope on east side of pad indicated with dashed green line.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



13. Run-on diversion ditch on east side of pad looking north.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



14. Run-on diversion ditch on east side looking south.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



15. Location where run-on diversion ditch meets well pad.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



16. Reclamation vegetation near southeast corner of pad.


Inspection Photos

Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732

API # 05-083-06686, 05-083-06687

Inspector Name: James Blair. Inspection Date: 02/10/2026

Inspection Doc #:72110021



17. Reclamation vegetation on west side of pad.

Inspection Photos  
Kinder Morgan Goodman Point 20 and Goodman Point 21. Loc. # 419732  
API # 05-083-06686, 05-083-06687  
Inspector Name: James Blair. Inspection Date: 02/10/2026  
Inspection Doc #:72110021



18. Reclamation vegetation on south edge of pad.