

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2026

Submitted Date:

02/12/2026

Document Number:

721100121

FIELD INSPECTION FORM

Loc ID: 419732 Inspector Name: Blair, Jamie On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 46685
 Name of Operator: KINDER MORGAN CO2 CO LLC
 Address: 1001 LOUISIANA ST SUITE 1000
 City: HOUSTON State: TX Zip: 77002

Findings:
18 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419724	WELL	PR	06/01/2025	CO2	083-06686	GOODMAN POINT (GP) 20	PR
419725	WELL	TA	11/01/2018	CO2	083-06687	GOODMAN POINT (GP) 21	TA

General Comment:

[Southwest Compliance Specialist Jamie Blair performed a compliance inspection and audit on Tuesday, February 10, 2026. Photos are included as an attachment.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Well location signs near entrance by flow line assemblies near gate for GP 20 and GP 21. Photos 1 and 2.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	OK		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-882-5522 = 24 hour 911 = emargency.		Date:
Corrective Action:			Date:
Good Housekeeping:			
Type	TRASH		
Comment:	Rags on GP-21. photo 9.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Broken valve by flow line assembly. Photo 4.		
Corrective Action:	Restore to service or store off site if no longer needed for operations to comply with 606.		Date: 02/19/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Cattle panel around GP20 flow line.		
Corrective Action:			Date:
Equipment:			
corrective date			
Type: Bradenhead	# 2		
Comment:	Accessible.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	From GP-20 wellhead to ground with 6" stainless flowlinen~20 ft long. GP-20 and GP-21 flow lines behind barricade near entrance by well signs.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Solar/telemetry		

Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Wellheads		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	None found.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	1000 GAL	STEEL AST		37.415270,-108.815418
Comment:	Produced water and diethylene glycol.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Skid-mounted metal tank with expanded metal top beneath tank. Is empty.			
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
083-06686

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 419724 Type: WELL API Number: 083-06686 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419725 Type: WELL API Number: 083-06687 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment: 10/14/2025 MIT Date

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Run-on diversion on east side of pad is functioning. Photos.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

ECMC Comments

Comment	User	Date
Remove to off site or return to service broken gate valve to comply with 606. See photos 4.	blairj1	02/10/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100124	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447635