

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2026

Submitted Date:

02/12/2026

Document Number:

693201215

## FIELD INSPECTION FORM

Loc ID 324641 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 34162  
Name of Operator: GILS HOT OIL SERVICE  
Address: P O BOX 418  
City: STRASBURG State: CO Zip: 80136

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard	970-989-3092	G.Richard.Murray@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212246	WELL	PR	05/01/2021	OW	057-06139	STATE 5 (OWP)	PA

**General Comment:**

Well is part of the Orphan Well Program.  
Inspection is to verify well was plugged and capped on 8/29/2025.  
ECMC OWP staff witnessed plugging operations

**Inspected Facilities**

Facility ID: 212246 Type: WELL API Number: 057-06139 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Snow Consulting Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 457 Cement Volume (sx): 82

Good Return During Job: YES Cement Type: type 2

Comment: See Form 6S and WBD. Well Capped on 8/29/2025

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693201216	WBD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447711</a>
693201217	Well marker	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447712">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7447712</a>