

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>02/12/2026</u> Submitted Date: <u>02/12/2026</u> Document Number: <u>719001376</u>
FIELD INSPECTION FORM			

Loc ID 326499 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89101	WELL	PR	09/01/2024	CBM	067-08205	ALICE LORENZ 2	PR

General Comment:

[Inspection Report Summary](#)
 On 2/12/26 | Inspector Charles Garcia conducted an on-site follow up inspection.
 Location: ALICE LORENZ 2
 Operator: Simcoe LLC
 API#: 067-08205
 County: LaPlata
 All prior CA's still stand
 DOC#719001252
 FIR#404542780
 CA RESOLVED SEE LOCATION PICTURES

Location

Overall Good:

Emergency Contact Number:

Comment: Contact # 970-247-6916
Emergency #911

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.205000,-107.781300

Comment: 21 BBL PRODUCED WATER TANK NO PAINT ON TOP OF TANK STARTING TO RUST Corrective Action: 600.b MAINTAIN TANK PAINT CA RESOLVED SEE LOCATION PICTURES

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

