

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>02/12/2026</u> Submitted Date: <u>02/12/2026</u> Document Number: <u>719001379</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 333412 Inspector Name: GARCIA, CHARLES On-Site Inspection   
 2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10133  
 Name of Operator: HILCORP ENERGY COMPANY  
 Address: P O BOX 61229  
 City: HOUSTON State: TX Zip: 77208

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215068	WELL	PR	11/30/2004	CBM	067-06673	SCHALLES -A- 1	PR
292003	WELL	PR	07/01/2011	CBM	067-09387	FLAGG 6-3	PR

**General Comment:**

[Inspection Report Summary](#)  
 On 2/12/26 | Inspector Charles Garcia conducted an on-site follow up inspection.  
 Location: FLAGG 6-3, SCHALLES A #1  
 API# 067-09387  
 API# 067-09387  
 Operator: HILLCORP ENERGY COMPANY  
 County: LaPlata  
 GATE CAMB0 7708  
 DOC#719001219  
 FIR#404521668  
 CA RESOLVED DIRT BERM WAS DUG OUT AND BUILT AROUND LUBE OIL CONTAINER SEE LOCATION PICTURES

**Location**

Overall Good:

Emergency Contact Number:

Comment: 505-324-5170  
911 EMERGENCY

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Ancillary equipment

# 2

Comment: 2 LUBE OIL CONTAINERS FOR PTIME MOVERS 1 WITH SPILL PREVENTION 1 WITHOUT  
Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.  
Comply with rule 1002.f  
CA RESOLVED DIRT BERM WAS DUG OUT AND BUILT AROUND LUBE OIL CONTAINER SEE LOCATION PICTURES

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215068 Type: WELL API Number: 067-06673 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**BradenHead**

Date of Last Brhd Test: 06/19/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292003 Type: WELL API Number: 067-09387 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**BradenHead**

Date of Last Brhd Test: 11/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 37 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001380	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7449137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7449137</a>