

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/05/2026

Document Number:

710500699

**FIELD INSPECTION FORM**

Loc ID 384227 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Coleman, Chris		chris.coleman@state.co.us	
Costa, Ryan		ryan.costa@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212634	WELL	PA	09/10/2000	OW	061-05142	DAWSON UNIT 1	EI

**General Comment:**

This is an Environmental Inspection for the Dawson Unit 1 Plugged and Abandon, well location located in Kiowa County, Colorado.

This is a follow up to Reclamation Inspection(s), no. 713600600, 713600280, 690203948 and Environmental Inspection no. 700600420.

Location ID: 384227  
API #: 05-061-05142  
Pit Facility ID 115304  
Well plug date: 9/10/2000.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

DEBRIS

Comment: At the time of inspection, remnants of oilfield equipment were observed within the fenced boundary of the well location.

Comply with Rule 1004.

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

Crude Oil

Comment: At the time of inspection, impacted soils were observed within the fenced boundary of the historical well location. There is evidence of a prior excavation within the boundary however impacts to soils remain.

Reclamation Inspection document no. 713600600 comment states: There has been excavation and removal of impacted soils from the flowline area near the location. It is unknown if there was more than 10 cubic yards of impacted soil removed and Operator has not submitted Form 19 spill report. This will be referred to EPS Staff.

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 02/12/2026

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type LOCATION

Comment: There is an electrical fence surrounding the location to keep livestock from entering the location

Maintain Fencing and Comply with the fencing requirements per the 1002a rules

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Flow Line

#

Comment: Reclamation Inspection document no. 713600600 identifies: There is an abandoned flowline cellar that remains.

Corrective Action: Operator shall provide additional details for the flowline equipment, Operator shall identify if the equipment is abandoned or active. If the equipment is abandoned the Operator shall comply with Rule 1105. Flowline Abandonment.

Date: 03/12/2026

**Venting:**

Yes/No

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 212634 Type: WELL API Number: 061-05142 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
All ongoing/unaddressed comments, Corrective Actions (CAs), and Conditions of Approval (COAs) from previous Forms remain applicable.	sanchezcc	02/05/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404536178	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441960">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441960</a>
710500702	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441947">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441947</a>