

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/06/2026

Document Number:

710500718

**FIELD INSPECTION FORM**

Loc ID: 324797 Inspector Name: Sanchez, Chris On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10777

Name of Operator: RAMPIKE RESOURCES LTD

Address: 730 17TH STREET SUITE 999

City: DENVER State: CO Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone          | Email                       | Comment |
|----------------|----------------|-----------------------------|---------|
| Coleman, Chris |                | chris.coleman@state.co.us   |         |
| Waggoner, Kyle |                | kyle.waggoner@state.co.us   |         |
| Costa, Ryan    |                | ryan.costa@state.co.us      |         |
| Sharp, Neil    | (720) 464-7603 | nsharp@rampikeresources.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|------------------------|-------------|
| 212663      | WELL     | PR     | 11/01/2023  | OW         | 061-06023 | DAWSON A 1             | EI          |
| 324797      | LOCATION | AC     |             |            | -         | DAWSON A-619S45W 9NENW | EI          |

**General Comment:**

This is an Environmental Inspection for the Dawson "A" well location located in Kiowa County, Colorado and Complaint ID: 200452238.

Location ID: 324797  
API #: 05-061-06023  
Pit Facility ID: 115290  
Complaint ID: 200452238

**Location**

Overall Good:

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | BATTERY   |       |  |
| Comment:             | Placard at Tank Battery, Per rule 605.g. Upon form 9 approval, the Operator must update signage within 60 days. New Operator name and emergency contact will need to be installed at each well and tank battery site. |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | Placard at wellhead, Per rule 605.g. Upon form 9 approval, the Operator must update signage within 60 days. New Operator name and emergency contact will need to be installed at each well and tank battery site.     |       |  |
| Corrective Action:   |   | Date: |  |

|                                  |                      |  |                            |
|----------------------------------|----------------------|--|----------------------------|
| <b>Emergency Contact Number:</b> |                      |  |                            |
| Comment:                         | <input type="text"/> |  |                            |
| Corrective Action:               | <input type="text"/> |  | Date: <input type="text"/> |

|                           |   |  |                         |
|---------------------------|---|--|-------------------------|
| <b>Good Housekeeping:</b> |   |  |                         |
| Type                      | DEBRIS  |  |                         |
| Comment:                  | At the time of inspection, undesirable weed species debris was observed within machine guarding |  |                         |
| Corrective Action:        | Remove debris and Comply with Rule 606.   |  | Date: <u>02/13/2026</u> |

Overall Good:

|                    |  |        |                         |
|--------------------|--|--------|-------------------------|
| <b>Spills:</b>     |  |        |                         |
| Type               | Area   | Volume |                         |
| Crude Oil          | WELLHEAD   |        |                         |
| Comment:           | At the time of inspection, impacts to soils were observed at the wellhead. Operator shall securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. |        |                         |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. If the Impacts to soils meet any of the criteria listed in 912.b. Operator shall file an Initial Form 19-I and contact area EPS for directives  |        | Date: <u>02/13/2026</u> |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| <b>Venting:</b>    |                      |       |  |
| Yes/No             |                      |       |  |
| Comment:           | <input type="text"/> |       |  |
| Corrective Action: |                      | Date: |  |

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| <b>Flaring:</b>    |                      |       |  |
| Type               |                      |       |  |
| Comment:           | <input type="text"/> |       |  |
| Corrective Action: |                      | Date: |  |

**Inspected Facilities**

Facility ID: 212663 Type: WELL API Number: 061-06023 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324797 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User      | Date       |
|---|-----------|------------|
| <p>ECMC Complaint ID: 200452238,</p> <p>Location of Concern: lat. 38.42231, long. -102.466 il leaking from tank head,</p> <p>Details: in one of my cattle pastures, this oil well has a leak. as you can see from the ground, the soil is contaminated &amp; it has leaked for some time.</p> | sanchezcc | 02/06/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404536185    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441966">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441966</a> |
| 710500720    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441944">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7441944</a> |