

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/05/2026

Submitted Date:

02/05/2026

Document Number:

720800272

FIELD INSPECTION FORM

Loc ID 433993 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433993	LOCATION	CL			-	State 2-36-9-61	

General Comment:

[This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: Production Tanks and Propane Tanks remain on Location

Corrective Action: Comply with Rule 606 and 1004

Date: 03/05/2026

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Barbed Wire

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 433993 Type: LOCATION API Number: - Status: CL Insp. Status:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine Field Compliance Audit - Unused Production Tanks and Propane Tanks remain on Location; wells have been Plugged and Abandoned. Tanks remain on Location. Comply with Rules 606 and 1004. Three months to remove surface equipment has passed.	petrie	02/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404536227	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442011
720800273	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7442008