

Final Reclamation and Stormwater Inspection

February 5, 2026

Operator: KP KAUFFMAN COMPANY INC

Location ID: 318320

Well Name: CHAMPLIN 86 AMOCO B #3

Inspection Document #: 718601359

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #3
Location ID: 318320



Photo 1. Looking south down the former access road. A stormwater ditch now runs through the access road. See photo 14.



Photo 2. Looking south down the former access road path. this area has been disturbed subsequent to oil and gas development. See photo 14.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #3
Location ID: 318320



Photo 3. Ditch and detention pond.



Photo 4. Looking southeast down the access road towards the well location. Gravel remains on the access road. Very little desirable vegetation is present on the access road. Undesirable weed kochia is present throughout the access road and not reflective of the surrounding vegetation.

Inspection Photos

Location Name: CHAMPLIN 86 AMOCO B #3

Location ID: 318320



Photo 5. Looking west from the access road near the wellhead. A metal fence, electrical meter and post remain on the location.



Photo 6. Photo taken in side the metal fence near the electric box. Cut off and exposed wires are present sticking out of the ground.



Inspection Photos

Location Name: CHAMPLIN 86 AMOCO B #3

Location ID: 318320



Photo 7. Looking southeast across the location. Vegetation on the location is primarily undesirable weed kochia and is not reflective of the surrounding reference area. A patch of desirable perennial vegetation such as *Thinopyrum intermediumis* present around the wellbore. Gravel remains on the former access road.



Photo 8. Photo taken on the access road to the southwest of the wellbore. List B noxious weeds *Carduus nutans* (musk thistle) and *Onopordum acanthium* (scotch thistle) are present throughout the location, including live rosettes.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #3
Location ID: 318320



Photo 9. Looking northwest across the location from the southeast edge. See photo 7 comments. List B noxious weed scotch thistle is visible in this photo.



Photo 10. Looking east from the wellbore. See photo 7 comments.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #3
Location ID: 318320



Photo 11. Looking west from the wellbore. See photo 7 comments.



Photo 12. Reference vegetation to the southeast of the well location.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #3
Location ID: 318320



Photo 13. Google earth aerial imagery taken 05/2018.
Illustration location access road while the well was active.



Photo 14. Google earth aerial imagery taken 04/2022. A stormwater ditch and basin unrelated to oil and gas was installed near the location. A 130' portion of the former access road (blue box) has been disturbed by non oil and gas activities.

