

Final Reclamation and Stormwater Inspection

February 5, 2026

Operator: KP KAUFFMAN COMPANY INC

Location ID: 317696

Well Name: CHAMPLIN 86 AMOCO B #1

Inspection Document #: 718601357

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #1
Location ID: 317696



Photo 1. Looking south across the location. Gravel remains on the location and it does not appear that reclamation was conducted.



Photo 2. Looking south across the wellhead. Equipment and debris remains on the location including rebar, pipe joint, boards and a pipe in the ground.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #1
Location ID: 317696



Photo 3. Oil and gas equipment and open pipe (red circle) remains on location.



Photo 4. Looking north from the wellbore. Gravel remains on the location and the location size has not been reduced. It does not appear that reclamation was conducted on location.

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #1
Location ID: 317696



Photo 5. Looking west from the wellbore. See photo 4 comments.



Photo 6. Looking south from the wellbore. See photo 4 comments.

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #1
Location ID: 317696



Photo 7. Looking east from the wellbore. See photo 4 comments.



Photo 8. Reference vegetation to the north of the well location.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO B #1
Location ID: 317696



Photo 9. Google earth aerial imagery taken 11/2025. Location (red circle) should be reclaimed leaving roads at pre disturbance width (two track width).



Photo 10. Historical imagery taken 08/1971. Access roads appear to be preexisting to oil and gas (green arrows) . The wide hilltop location/area is not observed in pre-oil and gas imagery. Approximate location (red circle).

