

Interim Reclamation and Stormwater Inspection

February 5, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 475443

Well Name: Miles/

Inspection Document #: 718601369

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC




COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Miles/
Location ID: 475443



Feb 5, 2026
176° S
ECMC

Photo 1. Looking south at the flowline riser station. The equipment is located approximately 250ft northwest of well API 123-07779.



Feb 5, 2026
79° E
ECMC

Photo 2. Photo taken looking east at the west side of the equipment. Leaking joints (red circle) and stained soil (blue circles) are present on the equipment.



Inspection Photos
Location Name: Miles/
Location ID: 475443



Photo 3. Photo taken at the south side of equipment. Stained soil/ oily buildup around joint (blue circle).




Photo 4. photo taken looking west at south side of equipment. Leaking joints (red circle) and stained soil (blue circles) are present on the equipment.

