

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2026

Submitted Date:

02/13/2026

Document Number:

693201249

FIELD INSPECTION FORM

Loc ID 312929 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10677
Name of Operator: WOLVERINE RESOURCES LLC
Address: 109 EAST 17TH STREET #430
City: CHEYENNE State: WY Zip: 82001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard	970-989-3092	G.Richard.Murray@state.co.us	
Rosenkrance, Todd		todd.rosenkrance@state.co.us	PM

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222878	WELL	SI	08/01/2019	GW	081-06238	FEDERAL LAND BANK 23-1 (OWP)	PA

General Comment:

Well is part of the ECMC Orphan Well Program.
Inspection is to verify well was plugged and capped on 12/18/2025.
location equipment, flowlines and tanks have been removed from location.
ECMC OWP staff witnessed plugging operations.

Inspected Facilities

Facility ID: 222878 Type: WELL API Number: 081-06238 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Snow Consulting Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7509 Cement Volume (sx): 234

Good Return During Job: YES Cement Type: Type 2

Comment: See Form 6S and WBD. Well Capped on 12/18/2025

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693201250	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7449531
693201251	WBD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7449532