

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Feb 9, 2026 at 2:09:51 PM
+40.111101,-108.219382
244° SW
CR-71
Rio Blanco County
ECMC



Feb 9, 2026 at 2:21:47 PM
+40.111029,-108.219714
166° S
CR-71
Rio Blanco County
ECMC

Photo # 1936 Entrance to location

Photo # 1964 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1937 Wellhead seal test using Additel681AEx pressure gauge



Photo # 1941 Wellhead seal test using Additel681AEx pressure gauge

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1944 Location



Photo # 1945 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1963 Location



Photo # 1973 NE corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1974 SE corner of location



Photo # 1975 SW corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1976 NW corner of location



Photo # 1949 Staining at heater treater

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1953 Staining at heater treater



Photo # 1955 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1958 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 1978 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1979 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Photo # 1994 Tunnel erosion near entrance to location

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1983 Unmarked deadman



Photo # 1980 Debris

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1984 Debris

Photo # 1985 Debris

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1986 Debris



Photo # 1987 Debris

Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT WYATT #25-34 PAD

Location ID: 316334

Date: 02/9/2026



Photo # 1988 Debris