

Inspection Photos

API: 009-05317

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 2/12/2026

County: BACA



Inspection Photos



Photo 1. Facing south toward the wellsite location. No production shown since 11/2023.



Inspection Photos



Photo 2. The netting on the open top tank is in disrepair.



Inspection Photos



Photo 3. Facing west at the location. Areas around the location have no vegetation.



Inspection Photos



Photo 3. Facing west at the location. Areas around the location have no vegetation.



Inspection Photos



Photo 5. Sign post at the meter shed does not contain the required signage information.

