

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2026

Submitted Date:

02/03/2026

Document Number:

699507799

FIELD INSPECTION FORM

Loc ID 478811 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10243
Name of Operator: GMT EXPLORATION COMPANY LLC
Address: 4949 S NIAGARA ST SUITE 250
City: DENVER State: CO Zip: 80237

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Blair, Max	720-862-4503	mblair@gmtexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478806	WELL	PR	07/01/2023	OW	039-06688	Vulcan 6-64 10-8 10HN	PR

General Comment:

Workover audit. Replace GL mandrels.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 478806 Type: WELL API Number: 039-06688 Status: PR Insp. Status: PR

Workover

Comment: At time of audit company representative informed me that they were POOH to inspect tubing and replace gas lift mandrels. At time of audit equipment on location was in need of secondary containment. Rig pump, tank, and accumulator were in need of grounding. At time of audit company representative informed me they would get the proper containment equipment for equipment on location. Before leaving location all equipment was grounded.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
This audit does not nullify any orders or corrective actions from the ECMC At time of inspection weather conditions were cold, light wind, overcast.	medinaj	02/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699507800	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7450385